


Accurate Lock and Hardware Co.

Manufacturers of
Custom Locks and Architectural Hardware

Amnie Place, Stamford, CT, 06902
(203) 348-8865 FAX (203) 348-8234
E-MAIL: Sales@AccurateLockandHardware.com
www.AccurateLockandHardware.com

8500-2 1/4 Backset Mortise Lock Installation Template

8525	FIG. 2	Knob/Lever Both Sides	1 1/4 Cylinder Hole Outside Only	Knob/Lever Both Sides	1 1/4 Cylinder Hole Both Sides	1 1/4 Cylinder Hole Outside Only	5/8 Dia. Hole Turn Piece Inside Only	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	5/8 Dia. Hole Turn Piece Inside Only
8556	FIG. 3	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Em. Key Outside Only, When Ordered	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	5/8 Dia. Hole Turn Piece Inside Only
8522	FIG. 4	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Em. Key Outside Only, When Ordered	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	5/8 Dia. Hole Turn Piece Inside Only
8524	FIG. 5	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Em. Key Outside Only, When Ordered	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	5/8 Dia. Hole Turn Piece Inside Only
8539	FIG. 6	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Em. Key Outside Only, When Ordered	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	5/8 Dia. Hole Turn Piece Inside Only
8501	FIG. 7	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Em. Key Outside Only, When Ordered	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	5/8 Dia. Hole Turn Piece Inside Only
8502	FIG. 8	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Em. Key Outside Only, When Ordered	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	5/8 Dia. Hole Turn Piece Inside Only
8503	FIG. 9	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Knob/Lever Both Sides	Em. Key Outside Only, When Ordered	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	1 1/4 Cylinder Hole Outside Only	5/8 Dia. Hole Turn Piece Inside Only



LEVER x LEVER 8500 SERIES 2 1/4 BACKSET

Responsibility
Door And Frame Manufacturers Are Responsible For
Providing Adequate Construction Or Re-inforcement
For Proper Installation Of Hardware Shown.

DWG. NO. 8500-2250TEMP REV 10/6/08
FILE NAME: F:\ERP\08\ACQUAINT\8500_8500-TEMPLATES
F:\WEBFILES\TEMPLATES\8500\8500DL-2250TEMP